FREUDING
Für perfekte Räume!

Freuding Labors GmbH
Am Schleifwogackor 2
D-87778 Stetten (Allgäu)

Phone: +49 (0)8261 7676-0
mail@freuding.com
www.freuding.com

# CARE INSTRUCTIONS

**For plastic, stainless steel, wood, fiber-cement and mineral stone surfaces, as well as NT top panels.**

**IMPORTANT NOTE**
Improper cleaning or the use of unsuitable cleaning and care products can cause to permanent damage to the surface. Damage resulting from improper handling is not covered by warranty or guarantee claims. If you have any questions about cleaning or care, please do not hesitate to contact us. Thank you for your trust.

# GENERAL CARE INSTRUCTIONS

- ✓ Remove stains as soon as possible.
- ✓ Always use cleaning products according to the manufacturer's instructions.
- ✓ Wipe surfaces dry after cleaning.
- ✓ Before using a new cleaning product for the first time, test it on an inconspicuous area to ensure it is compatible with the material.
  With the right care, your surfaces will retain their high-quality appearance and functionality for years to come.

FREUDING
Für perfekte Räume!

## FIBER-CEMENT AND SOLID WOOD PANELS

The general care instructions apply to fiber-cement panels.

**Please note:**
Do not leave standing liquids, wet rags, or damp wipes on the surface as fiber-cement absorbs water. (Risks of swelling)
**Recommended annual cleaning**
Use protection liquid MZ047.02

## NT panels

The general care instructions apply to NT panels.

**Recommended annual cleaning**
Using protection liquid PZ144

FREUDING
Für perfekte Räume!

## FREUDING-CARE PRODUCTS QR-CODE-SAFETY DATA SHEET

**Art. MZ047.02**
protection liquid, 1 liter
**for wood and fiber-cement tops**

**Art. PZ144**
protection liquid, 1 liter
buffalo wax for
**NT panels**

## CARE INSTRUCTIONS FOR PROTECTION LIQUID MZ047 AND PZ144

Apply care products MZ047.02 and PZ144 in a thin, even layer using a clean, soft cloth in circular motions. Wipe off any excess product with a clean cloth. If the care product has become thick due to storage in a cold environment, remove the cap and place the container in lukewarm water.
Follow the safety instructions on the care product label.
Drying time: 12 hours
(Allow 12 hours drying time between each additional coat of the care product)

## MINERAL STONE

**Daily cleaning**

Clean with a soft cloth, water, and a little dish soap. A regular deep cleaning you can use a standard scouring cream.

**Remove the following stains immediately:**

Disinfectants, isopropanol, acetone, chloroform, acetic acid, ethanol, ethyl acetate, medical-grade iodine solution, methylene chloride, phenol solution, phosphoric acid, tetrahydrofuran, wash-resistant ink, acrylic

**Remove the following stains within 10 min.:**

Coffee, Coke, black tea, alkaline cleaners, amidosulfonic acid, chlorine bleach solutions, hair dye, caustic soda, phosphoric acid, hydrochloric acid, tartaric acid, hydrogen peroxide

## MINERAL STONE

Failure to follow these instructions may result in dull spots, roughness, and discoloration.

**Please note**

- Short-term heat resistance up to approx. 180 °C
- Use coasters when placing hot objects on the surface.
- Mineral stone products are not scratch-resistant. Minor scratches can often be properly sanded out.
- Dark or highly pigmented finishes are more susceptible to scratches, and we do not recommend these colors for horizontal surfaces.

## PLASTIC TOPS

**Daily Cleaning**

Clean with warm water and a little dish soap or a mild all-purpose cleaner. Then rinse with clean water and dry.

**Basic care**

Apply a suitable grease remover or kitchen cleaner, let it sit for a short time, and then rinse thoroughly with water. Repeat the cleaning process if necessary.

**Please avoid**

Steel wool, abrasive microfiber cloths,
furniture polishes and waxes, cleaning and polishing agents (e.g., Viss, ATA), cleaners containing ingredients such as Scotch-Brite, highly acidic cleaners (e.g., drain or oven cleaners)

## STAINLESS STEEL

**Daily cleaning**

Remove fingerprints with a dry or slightly damp cotton cloth. For heavier soiling, add a small amount of mild, grease-cutting dish soap to the water.

**Remove Limescale Deposits**

Lightly dampen a cloth with liquid detergent or, alternatively, a 25 % solution of heavily diluted vinegar, and let it sit for a short time. Wipe away any residue with clean water and dry.

**Please avoid:**

Microfiber cloths, scouring pads, steel wool, abrasive cleaners, oven cleaners, bleach (chlorine-based, oxygen-based), strong acids (e.g., hydrochloric acid, hydrofluoric acid, strong descalers), caustic soda, ammonia-based products, **CAUTION: Risk of rust:** AP surfaces must not be used with V2A panels.

**Always work in the direction of the grain.**

## FREUDING-CARING PRODUCTS QR-CODE-SAFETY DATA SHEET

| | |
|---|---|
| **Art. PZ148**<br>Care product-multiClean<br>300 g for<br>**plastic, stainless steel, mineral stone panels,**<br>for heavy soiling | **Art. PZ149**<br>Spray for **plastic surfaces,**<br>500 ml |
| **Art. PZ146.02**<br>cleaning milk<br>500 ml<br><br>**for plastic, stainless steel and mineral stone** | **Art. PZ145**<br>Spray for **stainless steel,**<br>400 ml |